

# Digi TX Firmware Release Notes

## Version 24.6.17.54 (June 2024)

### INTRODUCTION

---

Digi Accelerated Linux is an advanced, high-performance operating system for cellular routers. These are the release notes for the Digi Accelerated Linux (DAL) firmware release, which supports the Digi TX family of products listed below.

### SUPPORTED PRODUCTS

---

- Digi TX40
- Digi TX54
- Digi TX64
- Digi TX64 Rail

### KNOWN ISSUES

---

- The Serial status and statistics for the TX54 are incorrect on the Web UI and CLI. [DAL-5763]
- Health metrics are uploaded to Digi Remote Manager unless the **Monitoring > Device Health > Enable** option is de-selected and either the **Central Management > Enable** option is de-selected or the **Central Management > Service** option is set to something other than Digi Remote Manager. [DAL-3291]
- Due to changes in the firewall, it is currently not possible to bridge traffic from devices connected on an Ethernet port or Wi-Fi AP in a bridged interface to a remote IP device via a gateway connected to an Ethernet port in the same bridged interface. [DAL-9799]

### UPDATE BEST PRACTICES

---

Digi recommends the following best practices:

1. Test the new release in a controlled environment with your application before you deploy production devices.
2. Unless otherwise noted, apply updates in the following order:
  - a. Device firmware
  - b. Modem firmware
  - c. Configuration
  - d. Application

Digi recommends Digi Remote Manager for automated device updates. For more information, see the [Digi Remote Manager User Guide](#).

If you prefer manually updating one device at a time, follow these steps:

1. Log into the Web UI.
2. Navigate to the **System > Firmware Update** page.
3. Click on the **Download from Server** tab.
4. Select the appropriate firmware version.
5. Click **UPDATE FIRMWARE**.
6. The device will automatically reboot once the firmware update is complete.

### **Upgrading TX64 from releases 21.11.60.63 or earlier**

If you are upgrading your TX64 device by using the local Web UI, you must first upgrade to release **22.2.9.85** prior to upgrading to the current release.

### **Upgrading TX54 from releases 21.8.24.139 or earlier**

If you are upgrading your TX54 device by using the local Web UI, you must first upgrade to release **22.5.50.62** before upgrading to the current release.

## **TECHNICAL SUPPORT**

---

Get the help you need via our Technical Support team and online resources. Digi offers multiple support levels and professional services to meet your needs. All Digi customers have access to product documentation, firmware, drivers, knowledgebase, and peer-to-peer support forums. Visit us at <https://www.digi.com/support> to find out more.

## **CHANGE LOG**

---

**Mandatory release** - A firmware release with a critical or high security fix rated by CVSS score. For devices complying with ERC/CIP and PCIDSS, their guidance states that updates are to be deployed onto devices within 30 days of release

**Recommended release** - A firmware release with medium or lower security fixes or no security fixes

Note that while Digi categorizes firmware releases as mandatory or recommended, the decision on when to apply the firmware update must be made by the customer after appropriate review and validation.

## **Primary Responder (PR) Support**

---

From the 23.12.1.56 release, the TX54 and TX64 Primary Responder devices can now use the standard TX54 and TX64 firmware releases which support a Primary Responder (PR) mode. To update your PR device, you must first update it to the **23.9.20.67** PR firmware release and then update to the 23.12.1.56 firmware or later.

The PR mode should be auto-enabled when the device is updated.

## VERSION 24.6.17.54 (June 2024)

---

This is a **mandatory** release.

### NEW FEATURES

There are no new features in this release.

### ENHANCEMENTS

1. The **TX40 Wi-Fi** driver has been updated
  - a. Supports up to 64 client connections.
  - b. Can now support 2 Wi-Fi Client interfaces, one on the 2.4 GHz band and one on the 5 GHz band.  
  
In total, the TX40 can support up to 3 interfaces, with any combinations of Access Points and clients.
2. The **WAN-Bonding** support has been enhanced with the following updates
  - a. SureLink support.
  - b. Encryption support.
  - c. SANE client has been updated to 1.24.1.2.
  - d. Support for configuring multiple WAN Bonding servers.
  - e. Enhanced status and statistics.
  - f. The WAN Bonding status is now included in the metrics sent to Digi Remote Manager.
3. The **cellular** support has been enhanced with the following updates
  - a. The special PDP context handling for the TX64 5G (EM9191) modem which was causing issues with some carriers. A common method is now used to set the PDP context.
  - b. The cellular connection back-off algorithm has been removed as the cellular modems have built-in back off algorithms that should be used.
  - c. The cellular APN lock parameter has been changed to APN selection to allow the user to select between using the built-in Auto-APN list, the configured APN list or both.
  - d. The cellular Auto-APN list has been updated.
  - e. The MNS-OOB-APN01.com.attz APN has been removed from the Auto-APN fallback list.
4. The TX54 **Bluetooth scanner** support has been updated with new filtering and data forwarding options.
5. The **Wireguard** support has been updated to allow the user to generate a client configuration that can be copied onto another device.

This is done using the command `wireguard generate <tunnel> <peer>`

Extra information may be needed from the client depending on config:

- a. How the client machine connects to the DAL device. This is needed if the client is initiating any connections and there is no keepalive value.
- b. If the client generates their own private/public key, they will need to set add that to their configuration file.

If this is used with 'Device managed public key', every time a generate is called on a peer, a new private/public key is generated and set for that peer, this is because we do not store any private key information of any clients on the device.

6. The SureLink support has been updated to

- a. Shutdown the cellular modem before power cycling it.
  - b. Export the INTERFACE and INDEX environment variables so that they can be used in custom action scripts.
7. The **Default IP** network interface has been renamed to **Setup IP** in the Web UI.
8. The **Default Link-local IP** network interface has been renamed to **Setup Link-local IP** in the Web UI.
9. The uploading of device events to Digi Remote Manager has been enabled by default.
10. The logging of SureLink events has been disabled by default as it was causing the event log to be saturated with test pass events.  
SureLink messages will still appear in the system message log.
11. The **show surelink** command has been updated.
12. The status of the System Watchdog tests can now be obtained via Digi Remote Manager, the Web UI and using CLI command show watchdog.
13. The Speedtest support has been enhanced with the following updates
  - a. To allow it to run on any zone with src\_nat enabled.
  - b. Better logging when a Speedtest fails to run.
14. The Digi Remote Manager support has been updated to only re-establish connection to Digi Remote Manager if there is a new route/interface it should utilize to get to Digi Remote Manager.
15. A new configuration parameter, **system > time > resync\_interval**, has been added to allow the user to configure the system time resynchronization interval.
16. Support for USB printers has been enabled. It is possible to configure to device to listen for printer requests via the socat command

```
socat - u tcp-listen:9100, fork, reuseaddr OPEN:/dev/usb/lp0
```
17. The SCP client command has been updated with a new legacy option to use the SCP protocol for file transfers instead of the SFTP protocol.
18. Serial connection status information has been added to the Query State response message that is sent to Digi Remote Manager.
19. Duplicate IPsec messages have been removed from the system log.
20. The debug log messages for the health metrics support have been removed.
21. The help text for the FIPS mode parameter has been updated to warn the user the device will automatically reboot when changed and that all configuration will be erased if disabled.
22. The help text for the SureLink delayed\_start parameter has been updated.
23. Support for the Digi Remote Manager RCI API compare\_to command has been added.

## SECURITY FIXES

1. The setting for **Client isolation on Wi-Fi Access Points** has been changed to be enabled by default. [DAL-9243]
2. The **Modbus** support has been updated to support the Internal, Edge and Setup zones by default. [DAL-9003]
3. The Linux kernel has been updated to 6.8. [DAL-9281]
4. The StrongSwan package has been updated to 5.9.13 [DAL-9153]  
[CVE-2023-41913](#) CVSS Score: 9.8 Critical

5. The OpenSSL package has been updated to 3.3.0. [DAL-9396]
6. The OpenSSH package has been updated to 9.7p1. [DAL-8924]  
[CVE-2023-51767](#) CVSS Score: 7.0 High  
[CVE-2023-48795](#) CVSS Score: 5.9 Medium
7. The DNSMasq package has been updated to 2.90. [DAL-9205]  
[CVE-2023-28450](#) CVSS Score: 7.5 High
8. The rsync package has been updated 3.2.7 for the TX64 platforms. [DAL-9154]  
[CVE-2022-29154](#) CVSS Score: 7.4 High
9. The udhcpd package has been updated to resolve a CVE issue. [DAL-9202]  
[CVE-2011-2716](#) CVSS Score: 6.8 Medium
10. The c-ares package has been updated to 1.28.1. [DAL9293-]  
[CVE-2023-28450](#) CVSS Score: 7.5 High
11. The jerryscript package has been updated to resolve a number CVEs.  
[CVE-2021-41751](#) CVSS Score: 9.8 Critical  
[CVE-2021-41752](#) CVSS Score: 9.8 Critical  
[CVE-2021-42863](#) CVSS Score: 9.8 Critical  
[CVE-2021-43453](#) CVSS Score: 9.8 Critical  
[CVE-2021-26195](#) CVSS Score: 8.8 High  
[CVE-2021-41682](#) CVSS Score: 7.8 High  
[CVE-2021-41683](#) CVSS Score: 7.8 High  
[CVE-2022-32117](#) CVSS Score: 7.8 High
12. The AppArmor package has been updated to 3.1.7. [DAL-8441]
13. The following iptables/netfilter packages have been updated [DAL-9412]
  - a. nftables 1.0.9
  - b. libnftnl 1.2.6
  - c. ipset 7.21
  - d. conntrack-tools 1.4.8
  - e. iptables 1.8.10
  - f. libnetfilter\_log 1.0.2
  - g. libnetfilter\_cttimeout 1.0.1
  - h. libnetfilter\_cthelper 1.0.1
  - i. libnetfilter\_conntrack 1.0.9
  - j. libnfnetlink 1.0.2
14. The following packages have been updated [DAL-9387]
  - a. libnl 3.9.0
  - b. iw 6.7
  - c. strace 6.8
  - d. net-tools 2.10
  - e. ethtool 6.7
  - f. MUSL 1.2.5

15. The http-only flag is now being set on Web UI headers. [DAL-9220]

## BUG FIXES

1. The **WAN Bonding** support has been updated with the following fixes
  - a. The client is now automatically restarted when client configuration changes are made. [DAL-8343]
  - b. The client is now automatically restarted if it has stopped or crashed. [DAL-9015]
  - c. The client is now not restarted if an interface goes up or down. [DAL-9097]
  - d. The sent and receive statistics has been corrected. [DAL-9339]
  - e. The link on the Web UI dashboard now takes the user to the Web-Bonding status page instead of the configuration page. [DAL-9272]
  - f. The CLI show route command has been updated to show the WAN Bonding interface. [DAL-9102]
  - g. Only the required ports rather than all ports are now opened in the firewall for incoming traffic in the Internal zone. [DAL-9130]
  - h. The show wan-bonding verbose command has been updated to comply with style requirements. [DAL-7190]
  - i. Data was not being sent through the tunnel due to an incorrect route metric. [DAL-9675]
  - j. The show wan-bonding verbose command. [DAL-9490, DAL-9758]
  - k. Reduced memory usage that causes issues on some platforms. [DAL-9609]
2. The **SureLink** support has been updated with the following fixes
  - a. An issue where re-configuring or remove static routes could cause routes being incorrectly added to the routing table has been resolved. [DAL-9553]
  - b. An issue where static routes were not being updated if the metric was configured as 0 has been resolved. [DAL-8384]
  - c. An issue where the TCP test to a hostname or FQDN can fail if the DNS request goes out of the wrong interface has been resolved. [DAL-9328]
  - d. An issue where disabling SureLink after an update routing table action leaves orphaned static routes has been resolved. [DAL-9282]
  - e. An issue where the show surelink command displaying incorrect status has been resolved. [DAL-8602, DAL-8345, DAL-8045]
  - f. An issue with SureLink being on enabled on LAN interfaces causing issues with tests being run on other interfaces has been resolved. [DAL-9653]
3. An issue with the HW encryption on the TX54 platforms that was introduced in the 24.3 release has been resolved. [DAL-9682]
4. An issue where IP packets could be sent out of the wrong interface, including those with private IP addresses which could lead to being disconnected from the cellular network has been resolved. [DAL-9443]
5. The SCEP support has been updated to resolve an issue when a certificate has been revoked. It will now perform a new enrollment request as the old key/certificates are no longer considered secure to perform a renewal. Old revoked certificates and keys are now removed from the device. [DAL-9655]

6. The Wi-Fi driver support for the TX54 and TX64 platforms has been updated to improve performance. [DAL-9060]
7. An issue with the TX64 where the device can crash when connecting to a Wi-Fi Access Point has been resolved. [DAL-9317]
8. An issue with how OpenVPN generated in server certificates has been resolved. [DAL-9750]
9. An issue where Digi Remote Manager would continue to display a device as connected if it had been booted locally has been resolved. [DAL-9411]
10. An issue with TX40 5G units outside of North America selecting an incorrect generic cellular firmware image has been resolved. [DAL-9266]
11. An issue with the TX40 5G units modem VoLTE and SIM hotswap settings being re-enabled after a carrier switch which resulted in longer connection times. [DAL-9264, DAL-9265]
12. An issue with the TX40 where changing the location service configuration could cause the cellular modem to disconnect has been resolved. [DAL-9201]
13. An issue where TX64 could not always connect to Wi-Fi Access Points using DFS channels has been resolved. [DAL-9298]
14. An issue with SureLink on IPsec tunnels using strict routing has been resolved. [DAL-9784]
15. A race condition when an IPsec tunnel is brought down and reestablished quickly could prevent the IPsec tunnel coming up has been resolved. [DAL-9753]
16. An issue when running multiple IPsec tunnels behind the same NAT where only interface could come up has been resolved. [DAL-9341]
17. An issue with IP Passthrough mode where the cellular interface would be brought down if the LAN interface goes down which meant the device was no longer accessible via Digi Remote Manager has been resolved. [DAL-9562]
18. An issue with multicast packets not being forwarded between bridge ports has been resolved. This issue was introduced in DAL 24.3. [DAL-9315]
19. An issue where an incorrect Cellular PLMID was being displayed has been resolved. [DAL-9315]
20. An issue with an incorrect 5G bandwidth being reported by the TX64 5G devices has been resolved. [DAL-9249]
21. An issue with selecting 5G\_SA mode with the on the TX64 5G with the EM9191 modem running the 03.14.10 firmware has been resolved. [DAL-9346]
22. An issue with the RSTP support where it may initialize correct in some configurations has been resolved. [DAL-9204]
23. An issue where a device would attempt to upload the maintenance status to Digi Remote Manager when it is disabled has been resolved. [DAL-6583]
24. An issue with the Web UI drag and drop support which could cause some parameters being incorrectly updated has been resolved. [DAL-8881]
25. An issue with the Serial RTS toggle pre-delayed not being honored has been resolved. [DAL-9330]
26. An issue with the Watchdog triggering a reboot when not necessary has been resolved. [DAL-9257]
27. An issue where modem firmware updates would fail due to the index of the modem changing during the update and the status result not being reported to Digi Remote Manager has been resolved. [DAL-9524]

28. An issue with the cellular modem firmware update on Sierra Wireless modems has been resolved. [DAL-9471]
29. An issue with how the cellular statistics were being reported to Digi Remote Manager has been resolved. [DAL-9651]

## **VERSION 24.3.28.88 (March 2024)**

---

This is a **mandatory** release.

### **NEW FEATURES**

30. Support for **WireGuard** VPNs has been added.
31. Support for a new **Ookla based speed test** has been added.  
Note: This is a Digi Remote Manager exclusive feature.
32. Support for **GRETap** Ethernet tunneling has been added.

### **ENHANCEMENTS**

1. The **WAN Bonding** support has been updated
  - a. Support for a WAN Bonding backup server has been added.
  - b. The WAN Bonding UDP port is now configurable.
  - c. The WAN Bonding client has been updated to 1.24.1
2. Support for configuring which **4G** and **5G cellular bands** can and cannot be used for a cellular connection has been added.  
Note: This configuration should be used with care as it could lead to poor cellular performance or even preventing the device from connecting to the cellular network.
3. The **System Watchdog** has been updated to allow for monitoring of interfaces and cellular modems.
4. The **DHCP server support** has been updated
  - a. To offer a specific IP address for a DHCP request received on a particular port.
  - b. Any requests for the **NTP server** and **WINS server options** will be ignored if the options is configured to **none**.
5. Support for **SNMP traps** to be sent when an event occurs has been added. It can be enabled on a per-event type basis.
6. Support for **Email notifications** to be sent when an event occurs has been added. It can be enabled on a per-event type basis.
7. A button has been added to the Web UI **Modem Status** page to update the modem to the latest available modem firmware image.
8. The OSPF support has been updated to add the capability to link OSPF routes through a DMVPN tunnel. There are two new configuration options
  - a. A new option has been added to **Network > Routes > Routing services > OSPFv2 > Interfaces > Network type** to specify the network type as a DMVPN tunnel.
  - b. A new Redirect setting has been added to **Network > Routes > Routing services > NHRP > Network** to allow redirection of packets between spokes.
9. The location service has been updated



- a. To support an interval\_multiplier of 0 when forwarding NMEA and TAIP messages. In this case, the NMEA/TAIP messages will be forwarded immediately rather than caching and waiting for the next interval multiple.
  - b. To only display the NMEA and TAIP filters depending on the select type.
  - c. To display the HDOP value in Web UI, **show location** command and in the metrics pushed up to Digi Remote Manager.
10. A configuration option has been added to the Serial interface support to disconnect any active sessions if the serial port DCD or DSR pins are disconnected.  
A new CLI command **system serial disconnect** has been added to support this.  
The Serial status page in the Web UI has also been updated with the option.
  11. The Digi Remote Manager keepalive support has been updated to more quickly detect stale connections and so can recover the Digi Remote Manager connection more quickly.
  12. The redistribution of connected and static routes by BGP, OSPFv2, OSPFv3, RIP and RIPng has been disabled by default.
  13. The **show surelink** command has been updated to have a summary view and an interface/tunnel specific view.
  14. The **Web UI serial status page** and the **show serial** command have been updated to display the same information. Previously some information was only available on one or the other.
  15. The **LDAP support** has been updated to support a group name alias.
  16. Support for connecting a **USB printer** to a device via a USB port has been added. This feature can be used via Python or socat to open a TCP port to process printer requests.
  17. The default timeout of the Python digidevice cli.execute function has been updated to 30 seconds to prevent command timeouts on some platforms.
  18. The Verizon 5G V5GA01INTERNET APN has been added to the fallback list.
  19. The help text for modem antenna parameter has been updated to include a warning that it may cause connectivity and performance issues.
  20. The help text for the DHCP hostname option parameter has been updated to clarify its use.

## SECURITY FIXES

1. The Linux kernel has been updated to version 6.7 [DAL-9078]
2. The Python support has been updated to version 3.10.13 [DAL-8214]
3. The Mosquitto package has been updated to version 2.0.18 [DAL-8811]  
[CVE-2023-28366](#) CVSS Score: 7.5 High
4. The OpenVPN package has been updated to version 2.6.9 [DAL-8810]  
[CVE-2023-46849](#) CVSS Score: 7.5 High  
[CVE-2023-46850](#) CVSS Score: 9.8 Critical
5. The rsync package has been updated to version 3.2.7 [DAL-9154]  
[CVE-2022-29154](#) CVSS Score: 7.4 High  
[CVE-2022-37434](#) CVSS Score: 9.8 Critical  
[CVE-2018-25032](#) CVSS Score: 7.5 High
6. The DNSMasq package has been patched to resolve CVE-2023-28450. [DAL-8338]  
[CVE-2023-28450](#) CVSS Score: 7.5 High

7. The udhcpc package has been patched to resolved CVE-2011-2716. [DAL-9202]  
[CVE-2011-2716](#) CVSS Score: 6.8 Medium
8. The default SNMP ACL settings have been updated to prevent access via External zone by default if the SNMP service is enabled. [DAL-9048]
9. The netif, ubus, uci, libubox packages have been updated to OpenWRT version 22.03 [DAL-8195]

## BUG FIXES

1. The following **WAN Bonding** issues have been resolved
  - a. The WAN Bonding client is not restarted if the client stops unexpectedly. [DAL-9015]
  - b. The WAN Bonding client was being restarted if an interface went up or down. [DAL-9097]
  - c. The WAN Bonding interface staying disconnected if a cellular interface cannot connect. [DAL-9190]
  - d. The **show route** command not displaying the WAN Bonding interface. [DAL-9102]
  - e. The **show wan-bonding** command displaying incorrect interface status. [DAL-8992, DAL-9066]
  - f. Unnecessary ports being opened in the firewall. [DAL-9130]
  - g. An IPsec tunnel configured to tunnel all traffic whilst using a WAN Bonding interface causing the IPsec tunnel to not pass any traffic. [DAL-8964]
2. An issue where **data metrics** being uploaded to Digi Remote Manager being lost has been resolved. [DAL-8787]
3. A Wi-Fi DMA issue that could cause the TX54 device to crash has been resolved. [DAL-9250]
4. An issue that caused **Modbus RTUs** to unexpectedly timeout has been resolved. [DAL-9064]
5. An **RSTP** issue with the bridge name lookup has been resolved. [DAL-9204]
6. The following issues with cellular status information have been resolved
  - a. Cellular signal strength percentage not being reported correctly. [DAL-8504]
  - b. Cellular signal strength percentage being reported by the /metrics/cellular/1/sim/signal\_percent metric. [DAL-8686]
  - c. The 5G signal strength being reported for the TX40 5G devices. [DAL-8653]
  - d. The 5G bandwidth being reported for the TX64 5G devices. [DAL-9249]
7. The following issues with the SNMP Accelerated MIB have been resolved
  - a. The cellular tables not working correct on devices with cellular interfaces not called “modem” has been resolved. [DAL-9037]
  - b. Syntax errors that prevented if from being correctly parsed by SNMP clients. [DAL-8800]
  - c. The runValue table not being correctly indexed. [DAL-8800]
8. The following PPPoE issues have been resolved
  - a. The client session was not being reset if the server goes away has been resolved. [DAL-6502]
  - b. Traffic stopping being routed after a period of time. [DAL-8807]
9. An issue with the DMVPN phase 3 support where firmware rules needed to the disabled in

- order to honor default routes inserted by BGP has been resolved. [DAL-8762]
10. An issue with the DMVPN support taking a long time to come up has been resolved. [DAL-9254]
  11. The Location status page in the Web UI has been updated to display the correct information when the source is set to user-defined.
  12. An issue with the Web UI and **show cloud** command displaying an internal Linux interface rather than the DAL interface has been resolved. [DAL-9118]
  13. An issue with the TX40 5G antenna diversity which would cause the modem to go into a “dump” state has been resolved. [DAL-9013]
  14. An issue where devices using a Viaero SIM could not connect to 5G networks has been resolved. [DAL-9039]
  15. An issue with the SureLink configuration migration resulting some blank settings has been resolved. [DAL-8399]
  16. An issue where configuration was been committed at boot-up after an update has been resolved. [DAL-9143]
  17. The **show network** command has been corrected to always display the TX and RX bytes values.
  18. The NHRP support has been updated to not log messages when disabled. [DAL-9254]

## DEPRECATION

1. LR54 and LR54W platforms are no longer supported.

## VERSION 23.12.1.61 (January 2024)

---

This is a **recommended** release.

### NEW FEATURES

There are no new features in this release.

### ENHANCEMENTS

There are no enhancements in this release.

### SECURITY FIXES

There are no security fixes in this release.

### BUG FIXES

1. An issue where an incorrect WAN Bonding status was being reported via the Web UI has been resolved. [DAL-8892]
2. The ITxPT GNSS version has been corrected to be v2.2.1. [DAL-8972, DAL-8990]

## VERSION 23.12.1.56 (December 2023)

---

This is a **mandatory** release.

### NEW FEATURES

1. Support for linking OSPF routes through a DMVPN tunnel has been added.

- a. A new configuration option **Point-to-Point DMVPN** has been added to **Network > Routes > Routing services > OSPFv2 > Interface > Network** parameter.
  - b. A new configuration parameter **redirect** has been added to the **Network > Routes > Routing services > NHRP > Network** configuration.
2. Support for the **Rapid Spanning Tree Protocol (RSTP)** has been added.
  3. Support for configuring the **TX54 Ignition Sense** as a **digital input** has been added.
  4. Support for **device initiated RealPort** connections has been added.

## ENHANCEMENTS

1. A new option **After** has been added to the **Network > Modems Preferred SIM** configuration to prevent a device from switching back to the preferred SIM for the configured amount of time.
2. The **WAN Bonding** support has been updated
  - a. New options have been added to the **Bonding Proxy** and **Client devices** configuration to direct traffic from specified network through the internal WAN Bonding Proxy to provide improved TCP performance through the WAN Bonding server.
  - b. New options have been added to set the **Metric** and **Weight** of the WAN Bonding route which can be used to control the priority of the WAN Bonding connection over other WAN interfaces.
3. A new DHCP server option to support BOOTP clients has been added. It is disabled by default.
4. Support for recognizing USB-based CAN serial adaptors from [Canable](#) and [ValueCAN](#) has been added.
5. The status of Premium Subscriptions has been added the System Support Report.
6. A new `object_value` argument have been added to the local Web API that can be used to configure a single value object.
7. The SureLink actions **Attempts** parameter has been renamed to the **SureLink Test failures** to better describe its use.
8. A new **vttysh** option has been added to the CLI to allow access to the **FRRouting** integrated shell.
9. A new **RealPort** option has been added to control the minimum TLS version that can be used.
10. A new **modem sms** command has been added to CLI for sending outbound SMS messages.
11. The maximum of number of Wi-Fi clients supported on the TX40 has been increased to 16.
12. A new **Authentication > serial > Telnet Login** parameter to been added to control whether a user must supply authentication credentials when opening a Telnet connection to direct access a serial port on the device.
13. The OSPF support has been updated to support the setting the Area ID to an IPv4 address or a number.
14. The mDNS support has been updated to allow a maximum TXT record size of 1300 bytes.
15. The migration of the SureLink configuration from 22.11.x.x or earlier releases has been improved.
16. A new **System → Advanced watchdog → Fault detection tests → Modem check and recovery** configuration setting has been added to control whether the watchdog will monitor the initialization of the cellular modem inside the device and automatically take recovery actions to reboot the system if the modem doesn't initialize properly (disabled by default)

## SECURITY FIXES

1. The Linux kernel has been updated to version 6.5 [DAL-8325]
2. An issue with sensitive SCEP details appearing the SCEP log has been resolved. [DAL-8663]
3. An issue where a SCEP private key could be read via the CLI or Web UI has been resolved. [DAL-8667]
4. The musl library has been updated to version 1.2.4 [DAL-8391]
5. The OpenSSL library has been updated to version 3.1.3 [DAL-8447]  
[CVE-2023-4807](#) CVSS Score: 7.8 High  
[CVE-2023-3817](#) CVSS Score: 5.3 Medium
6. The OpenSSH package has been updated to version 9.5p1 [DAL-8448]
7. The curl package has been updated to version 8.4.0 [DAL-8469]  
[CVE-2023-38545](#) CVSS Score: 9.8 Critical  
[CVE-2023-38546](#) CVSS Score: 3.7 Low
8. The frrouting package has been updated to version 9.0.1 [DAL-8251]  
[CVE-2023-41361](#) CVSS Score: 9.8 Critical  
[CVE-2023-47235](#) CVSS Score: 7.5 High  
[CVE-2023-38802](#) CVSS Score: 7.5 High
9. The sqlite package has been updated to version 3.43.2 [DAL-8339]  
[CVE-2022-35737](#) CVSS Score: 7.5 High
10. The netif, ubus, uci, libubox packages have been updated to OpenWRT version 21.02 [DAL-7749]

## BUG FIXES

1. An issue with DMVPN that cause NHRP routing through tunnels to Cisco hubs to be unstable has been resolved. [DAL-8668]
2. An issue that prevented the handling of incoming SMS message from Digi Remote Manager has been resolved. [DAL-8671]
3. An issue that could cause a delay in connecting to Digi Remove Manager when booting up has been resolved. [DAL-8801]
4. An issue with MACsec where the interface could fail to re-establish if the tunnel connection was interrupted has been resolved. [DAL-8796]
5. An intermittent issue with the SureLink restart-interface recovery action on an Ethernet interface when re-initializing the link has been resolved. [DAL-8473]
6. An issue that prevented the Autoconnect mode on a Serial port from reconnecting until the timeout had expired has been resolved. [DAL-8564]
7. An issue that prevented IPsec tunnels from being established through a WAN Bonding interface have been resolved. [DAL-8243]
8. An intermittent issue where SureLink could trigger a recovery action for an IPv6 interface even if no IPv6 tests were configured has been resolved. [DAL-8248]
9. An issue with SureLink custom tests has been resolved. [DAL-8414]
10. An issue with the TX40 5G unit not connecting to the Orange network in France has been resolved. [DAL-8512]

11. An issue with LDAP authentication not working when LDAP is the only configured authentication method has been resolved. [DAL-8559]
12. An issue with the Primary Responder (PR) mode not automatically enabling on some TX54 SKUs has been resolved. [DAL-8740]
13. An issue where local non-admin user passwords were not migrated after enabling Primary Responder mode has been resolved. [DAL-8740]
14. An issue where a disabled interface would show received/sent values of N/A in the Web UI Dashboard has been resolved. [DAL-8427]
15. An issue that prevented users from manually registering some Digi router types with Digi Remote Manager via the Web UI has been resolved. [DAL-8493]
16. An issue where the system uptime metric was reporting an incorrect value to Digi Remote Manager has been resolved. [DAL-8494]
17. An issue with TX54 Ethernet connectivity with Axoim devices has been resolved. [DAL-8499]
18. An issue where the wrong modem type was being reported to Digi Remote Manager for the TX64 5G wwan2 interface has been resolved. [DAL-8893]
19. An intermittent issue with migrating IPsec SureLink setting from devices running 22.11.x.x or earlier has been resolved. [DAL-8415]
20. An issue where SureLink was not reverting the routing metrics when failing back on an interface has been resolved. [DAL-8887]
21. An issue where the CLI and Web UI would not show the correct networking details when WAN Bonding was enabled has been resolved. [DAL-8866]
22. An issue with the show wan-bonding CLI command has been resolved. [DAL-8899]
23. An issue that prevent devices from connecting to Digi Remote Manager over a WAN Bonding interface has been resolved. [DAL-8882]

## **VERSION 23.9.20.67 (December 2023)**

---

This is a **recommended** release.

### **NEW FEATURES**

There are no new features with this release.

### **ENHANCEMENTS**

There are no enhancements with this release.

### **SECURITY FIXES**

There are no security fixes with this release.

### **BUG FIXES**

1. An issue with SureLink which would take the interface out of service with the first test failure if the first action is “Update Routing table” has been resolved. This could cause devices with one WAN interface to unnecessarily it’s lose interface connection. [DAL-8500]

## **VERSION 23.9.20.63 (October 2023)**

---

This is a **mandatory** release.

## NEW FEATURES

1. A new **Primary Responder** mode has been added which, when enabled, will increase the security suitable for devices with used on the FirstNet network or similar. For example, it will prevent shell access, disable older cryptographic functions and features that are no longer considered as safe.

For the PR devices (e.g. TX54-A146, TX54-A246, TX64-A141, TX64-A161-PR, TX64-R210-PR), this mode will be automatically enabled when updated to the 23.9.20.63 release and a FirstNet SIM is being used.

Note that the 23.9.20.63 release will be the final PR specific DAL firmware release. Going forward the PR devices will use the same DAL firmware release as the equivalent non-PR device.

2. Support for **MACsec (IEEE 802.1ae)** has been added.
3. Support for **DNS allow list** which allows the user to control which domains are accessible through the device has been added. By default, all domains are allowed.
4. A new **Status > Premium Features** Web UI page has been added that allows the user to see the available premium features available on the device and to import license files.
5. A link has been added to the Digi Remote Manager section on the Web UI Dashboard to register the device to Digi Remote Manager.

## ENHANCEMENTS

1. The **FIPS mode** support has been added to the TX54 and LR54 platforms.
2. The **Hotspot** support has been updated with the following functionality:
  - a. SessGarden/PSD2 support
  - b. UAM server configuration
3. The Web UI dashboard has been updated to combine the network interface and cellular modem details into a single panel. This frees up space for more platform specific panels.
4. Support has been added for a **DNS fallback server** which is used in the event that no configured or DHCP obtained DNS servers are available.
5. A new **Force link** parameter has been added for Ethernet interfaces that will force the interface to be up even if there is no Ethernet cable plugged in.
6. A new PDP context index parameter was added for when configuring an APN to control what PDP context the APN gets written to in the SIM.
7. Support for DHCP option 12 to support advertising the hostname over a cellular interface has been added.
8. The **persistent files directory** available in the Files tab in Digi Remote Manager have been renamed to **persistent-files**.
9. A new Containers configuration parameter has been added to allow the initial working directory within the Container to be configured.
10. The Containers status page in the Web UI has been updated to validate the name of the Container file being uploaded.
11. The Containers Clone DAL configuration setting has been changed to Clone host system libraries.

12. The SureLink logging has been updated for Cellular interface to better reflect the SureLink state and why SureLink tests were skipped.
13. WAN Bonding status and details have been added to the Support Report.
14. The Python MQTT module, paho-mqtt, has been updated to v1.6.1.
15. The Serial port support for ports configured with remote TCP listeners has been updated to utilize the SSL version specific in the Services > Web Administration > Minimum TLS version.
16. The ACCELERATED-MIB support by the devices has been updated with the following objects:
  - a. System information
  - b. Serial number
  - c. Firmware version
  - d. DAL model
  - e. Run time (runt) status and statistics – The user is able to configure which runt values are accessible through the MIB.
17. The Serial status page in the Web UI has been updated to display the Log button when in modem emulator mode.
18. The firmware update page in the Web UI has been updated to display the firmware build date.
19. The reported input voltage level and system and CPU temperature values are now limited to one decimal place.
20. The help text for the TACACS+ Authentication configuration has been updated to note that the # character cannot be used in the TACACS+ secret key.
21. The help text for the Cellular modem firmware update pop-up has been updated.
22. The help text in the Container configuration has been updated.
23. The APNs nrbroadband and NFOD-INET-APN01.com.attz has been added to the fallback list for AT&T SIMs.
24. The APNs iot.tmovholesale and fbb.home have been added to the fallback list for T-Mobile SIMs.
25. The PLMN and ICCID prefix list for T-Mobile SIMs have been updated.
26. A debug setting to allow DHCP relay support within in Sierra Wireless cellular modules has been added.

## **SECURITY FIXES**

1. The TX54 and LR54 platforms have been updated to use OpenSSL v3.1.1 [DAL-8062]
2. The OpenSSH package has been updated to version 9.3p2 [DAL-8097]  
[CVE-2023-38408](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H

## **BUG FIXES**

1. A Wi-Fi client issue where the device would not connect to an Access Point using the mixed mode PSK security option has been resolved. [DAL-8443]
2. An issue where the wrong destination IP address and MAC address being used for SureLink ping tests on GRE tunnels has been resolved. [DAL-8385]
3. An issue where cellular utilization reports in Digi Remote Manager would be skewed due to the device reporting incorrect Rx/Tx data usage metrics has been resolved. [DAL-8380]
4. An issue that prevent Over-the-Air cellular modem firmware updates from completing when



- initiated via Digi Remote Manager has been resolved. [DAL-DAL833, DAL-7885, DAL-7860]
5. A race condition that prevented the NTP server from starting if an active NTP sync was in progress has been resolved. [DAL-8122]
  6. An issue configuring Ethernet speeds other than Auto has been resolved. [DAL-7052, DAL-7868]
  7. An issue where the SureLink fail\_count metric was not being reported to Digi Remote Manager when the SureLink tests were passing has been resolved. [DAL-7975]
  8. An issue where the incorrect cellular carrier name being reported to Digi Remote Manager has been resolved. [DAL-7924]
  9. An issue where a device would not report the correct modem firmware version to Digi Remote Manager after an update was initiated by Digi Remote Manager has been resolved. [DAL-7983]
  10. An issue where WWAN2 cellular metrics being reported to Digi Remote Manager would sometimes overwrite the WWAN1 cellular metrics has been resolved. [DAL-7681]
  11. An issue where SureLink metrics for bridge interfaces were not being correctly reported to Digi Remote Manager has been resolved. [DAL-7990]
  12. An issue where the cellular APN metric was not being reported to Digi Remote Manager has been resolved. [DAL-8055]
  13. An issue where an AnywhereUSB warning message was being displayed on non AnywhereUSB devices has been resolved. [DAL-8000]
  14. An issue where the device could connect with the configured APN list out of order if previously connected with one of the configured APNs has been resolved. [DAL-8335]
  15. An issue with the TX54-A146 and TX54-A256 where the cellular modem could initialize in the wrong mode which would prevent it from connecting to the network has been resolved. [DAL-7923]
  16. An issue that prevent a device from connecting to the cellular network using a second SIM slot if multiple network interfaces were using per-SIM slot configuration has been resolved. [DAL-8115]
  17. An issue that prevented hotspots from initializing corrected when using a network bridge configuration has been resolved. [DAL-7985]

## **VERSION 23.6.1.120 (August 2023)**

---

This is a **recommended** release.

### **ENHANCEMENTS**

1. The nrbroadband APN has been added to AT&T fallback list.
2. New metrics being reported to Digi Remote Manager to track the number of disconnects on each WAN interface have been added.

### **BUG FIXES**

1. An issue that prevented WPA2 Enterprise AP & client-mode connections from working has been resolved. [DAL-8073]
2. An issue with the Wi-Fi 6 support on the TX64 has been resolved. [DAL-8171]
3. Support for automatically recognizing AT&T SIMs with ICCID prefix 890128 and PLMN ID 310280 has been added. [DAL-8038]

4. An issue where the cellular APN metric was not being reported to Digi Remote Manager with the 23.6.1.105 firmware has been resolved. [DAL-8055]
5. An issue where devices with multiple cellular modems would not report metrics for the secondary modem to Digi Remote Manager properly has been resolved. [DAL-7681]

## **VERSION 23.6.1.105 (July 2023)**

---

This is a **mandatory** release.

### **NEW FEATURES**

1. The ability to do a **SIM survey** on a device using Digi Remote Manager has been added. A connection will be attempted on each installed SIM and a report detailing the SIM connection details such as connection status, signal strength, APN used and cellular tower information is generated. The device will revert to the original setup once the SIM survey is complete.
2. A new serial port **modem emulator** mode to allow them to act as a dial-up modem emulator has been added.

### **ENHANCEMENTS**

1. Better support for updating cellular modem firmware using Digi Remote Manager has been added.
2. A new **VPN iptunnel open routing** configuration has been added to allow packets destined for an IP address which is not explicitly in the device's routing table to exit the VPN tunnel.
3. The following new datastream metrics being reported to Digi Remote Manager have been added:
  - cellular/x/sim/y/registration
  - eth/x/link
  - eth/x/surelink/rtt
  - eth/x/surelink/fail\_count
  - wifi/x
  - wifi-ap/x
  - vpn/ipsec/x/disconnects
  - sys/chassis/voltage
  - sys/chassis/temp
4. The device will immediately upload all health metrics to Digi Remote Manager when it establishes a connection for the first time. Previously it would take for the configured **Monitoring > Device Health** metric.
5. The device will now report the cellular modem IMEI to Digi Remote Manager even when there is no SIM installed in the device.
6. A SSH server configured on serial ports will now use any configured custom SSH options in **Services > SSH > Custom** configuration.
7. The Web UI dashboard has been updated to display the interface being used for the Digi Remote Manager connection.
8. A new TCP retry configuration has been added to control the number of times an unacknowledged TCP data packet will be transmitted before the configuration is considered

as lost. The default is 15 retries.

9. The help text in the Serial port modes have been updated for additional clarity.
10. The error message reported when a TACACS+ server cannot authorize the full CLI command due to the RFC length constraints has been updated.
11. A new serial port configuration setting has been added for serial ports in PPP dial-in mode to control whether a default route gets added for the PPP interface. The default is disabled.
12. The **Network > SD-WAN** configuration will not be displayed if the firmware does not support **WAN Bonding**.
13. A system log message will now be generated if WAN Bonding is enabled but unsubscribed.
14. A Support Report will be automatically generated in /opt/digi-support-watchdog-mem-full.bin before a device reboots due to a watchdog timeout.

## SECURITY FIXES

1. The Linux kernel has been updated to version 6.3 [DAL-7606]
2. The Busybox package has been updated to version 1.34.0 [DAL-7819]  
[CVE-2022-28391](#) CVSS Score: 8.8 High CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H
3. The OpenSSL package has been updated to 3.1.1 on the TX64 platforms and 1.1.1u on the TX54 and LR54 platforms. [DAL-7818]  
[CVE-2018-16395](#) CVSS Score: 9.8 Critical CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H
4. The libcurl package has been updated to 8.1.2 [DAL-7817]
5. The OpenSSH package has been updated to version 9.3p1 [DAL-7816]  
[CVE-2021-36368](#) CVSS Score: 3.7 Low CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:L/I:N/A:N
6. The libgmp package has been updated to version 6.2.1 [DAL-7820]  
[CVE-2021-43618](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H
7. The OpenVPN package has been updated to version 2.6.4 [DAL-7822]  
[CVE-2020-27569](#) CVSS Score: 7.5 CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:H/A:N  
[CVE-2020-7224](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2016-7798](#) CVSS Score:7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N
8. The StrongSwan package has been updated to version 5.9.10 [DAL-7823]
9. The DNSmasq package has been updated to version 2.89 [DAL-7533]  
[CVE-2021-45951](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-45952](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-45953](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-45954](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-45955](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-45956](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-45957](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H
10. Netifd, ubus, UCI and libublox have been updated to OpenWRT 19.07 [DAL-6766]

## BUG FIXES

1. An issue with Wi-Fi Hotspot not starting correctly if they were not linked to a network bridge has been resolved. [DAL-7623]

2. An incorrect SureLink status was being reported on IPsec and OpenVPN tunnels has been resolved. [DAL-7893]
3. An incorrect SureLink status was being reported when SureLink was disabled on a network interface has been resolved. [DAL-7552]
4. A SureLink issue where a skipped DNS tests could result in a SureLink failure has been resolved. [DAL-7814]
5. The following issues with SureLink configuration migration from 22.11 and older firmware has been resolved:
  - IPsec and OpenVPN configurations were not being migrated. [DAL-7747]
  - The success\_condition setting was not always being correctly migrated. [DAL-7803]
  - The update\_routing\_table action was being added but was not applicable to IPsec tunnels. [DAL-7892]
  - The SureLink ping test default packet size has been changed from 1 byte to 20 bytes as it was causing issues on some cellular networks. [DAL-7769]
6. The incorrect reporting of the cellular TAC when using a TX54 5G device has been resolved. [DAL-7941]
7. An issue with errant IPv6 packets being transmitted over a PPP dial-in serial port has been resolved. [DAL-7799]
8. A log message indicating that intelliFlow is unsubscribed will now only be logged if intelliFlow is enabled.
9. An issue where a device would report its MAC address as all zeros when it initially connects to Digi Remote Manager has been fixed. [DAL-1609]
10. An issue using BGP capability 70 on DMVPN hubs has been resolved. [DAL-7740]
11. An issue where a TX54 device getting stuck in a reboot loop if there are updated from 21.11 to 22.11 or 23.3 has been resolved. [DAL-7667]
12. An issue with LTE 4G connectivity with Bell Mobility SIMs has been resolved. [DAL-7350]
13. An issue that caused an error message in the system logs where the Web UI would try to obtain the WAN Bonding status before a user is authenticated.
14. An issue where SNMP wouldn't provide updated settings if a new hostname has been configured has resolved. [DAL-7442]
15. An issue with TX64 devices where /opt directory was not being created during manufacturing, resulting in the device not being able to store configuration changes has been resolved. [DAL-7586]
16. An OSPF issue that prevent IP networks being configured has been resolved. [DAL-7603]
17. A Wi-Fi issue that would prevent multiple SSIDs being scanned when DFS client mode was enabled has been resolved. [DAL-7608]
18. An issue in RealPort authentication has been resolved. [DAL-7651]
19. The following issues with the LM940 cellular modem have been resolved:
  - The LM940 cellular modem could be powered off after a cellular modem firmware update has been resolved. [DAL-7719]
  - The LM940 cellular modem could disappear from the USB bus after switching SIMs. [DAL-7638]

## VERSION 23.3.31.129 (April 2023)

---

This is a **mandatory** release.

### NEW FEATURES

1. The **SureLink** support has been updated.
  - The SureLink configuration has been moved from the IPv4 and IPv6 level configuration to interface level.
  - The recovery actions configuration has been changed to be list based so that you can configure a list of recovery actions to be taken on the configured number of SureLink test failures.
  - Support for custom tests and recovery actions have been added.
  - The **show surelink state** CLI command has been added to display the overall pass/fail status of the tests and recovery actions to be taken.

**Note: Due to the SureLink configuration changes, the SureLink configuration may be not fully migrated from previous releases. Digi recommends that you review the SureLink configuration before rolling out the 23.6.1.105 release to mission critical devices.**

2. **DMVPN phase 1 spoke** support with **NHRP** and **mGRE** including compatibility with Cisco DMVPN hubs has been added.
3. Support for using the **cellular** modem as a **time sync source** has been added.

### ENHANCEMENTS

1. **WAN Bonding** support has been updated
  - Options have been added to configure the mode for each tunneled interface and the overall mode.
  - Distance between the WAN bonding and Ethernet bonding settings have been added.
  - The saneclient has been updated to 20221103 for 5G and 1 Gbps performance.
  - A **show wan-bonding** CLI command has been added.
  - A new **Status > WAN Bonding** status page has been added to the Web UI.
2. The **Container** support has been updated
  - Containers can be configured to auto-start on boot with optional parameters and to restart if the container stops.
  - Configuration has been added to setup shared directories between the host file system and the container.
3. The Modem Manager package has been updated to 1.20.6. This includes
  - Improved 5G SA and NSA mode performance.
  - RSRP, RSRQ and SINR statistics for 5G SA mode connections.
  - Native multiplexing for dual-APN setups.
4. **mDNS** support has been disabled by default in order to improve cellular performance.
5. The **ITxPT** support has been updated to support IPv6 for the MQTT broker, GNSS services.
6. **US Cellular** consumer SIM support has been updated so that configured APNs are not

required.

7. A new setting to enable/disable **AT&T LWM2M** on the modem has been added. It is disabled by default.
8. The Web UI has been updated to display the system hostname (if configured) on the dashboard page.
9. The IPsec support has been updated to include SHA2 ciphers for IKEv2 IPsec tunnels.
10. **GlobalGIG** APNs have been added to the fallback APN list.

## SECURITY FIXES

1. The Linux kernel has been updated to 6.1. [DAL-7179]
2. The OpenSSL package has been updated to 3.0.8 on the TX64 platforms and 1.1.1t on the TX54 and LR54 platforms. [DAL-7261]

[CVE-2023-0401](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2023-0286](#) CVSS Score: 7.4 High CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:N/A:H

[CVE-2023-0217](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2023-0216](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2023-0215](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2022-4450](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2022-4304](#) CVSS Score: 5.9 Medium CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:N/A:N

[CVE-2022-4203](#) CVSS Score: 4.9 Medium CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:N/I:N/A:H

[CVE-2022-3996](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2023-0286](#) CVSS Score: 7.4 High CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:N/A:H

[CVE-2023-0215](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2022-4450](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2022-4304](#) CVSS Score: 5.9 Medium CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:N/A:N

3. The netifd package has been updated to 18.06. [DAL-6280]
4. The libexpat package has been updated to 2.5.0. [DAL-7082]  
[CVE-2022-23852](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2022-23990](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H  
[CVE-2022-22827](#) CVSS Score: 8.8 High CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H  
[CVE-2022-22826](#) CVSS Score: 8.8 High CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H  
[CVE-2022-22825](#) CVSS Score: 8.8 High CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H  
[CVE-2022-22824](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2022-22823](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2022-22822](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H
5. Wi-Fi pre-shared keys are now obfuscated in Digi Remote Manager. [DAL-7107]

## BUG FIXES

1. An issue with updating non-active firmware images on the EM9191 5G cellular modem has been resolved. [DAL-7451]
2. An issue preventing users from locking a device to use a blank APN has been resolved. [DAL-

7248]

3. An issue where Wi-Fi channel configuration options appearing as “None” has been resolved. [DAL-7482]
4. An issue that prevented the device from falling back to its local system time when running as a NTP server has been resolved. [DAL-7233]
5. An issue that prevented SIM failover when the device was configured with separate network interfaces set to by carrier instead of SIM slot has been resolved. [DAL-6910]
6. The 3 second stop/start delay when making configuration updates to the MQTT broker settings has been removed. [DAL-7104]
7. An issue with the **tail** CLI command where the match option would only work if the filter option is also set has been resolved. [DAL-7038]
8. An issue that prevented the WAN bonding interface appearing in the **show route** CLI command output. [DAL-6829]
9. An issue where the initial SureLink test would fail if the cellular modem is configured in passthrough mode has been resolved. [DAL-6224]
10. A GRE/IPsec routing problem with a Cisco peer using VTI configuration has been resolved. [DAL-6722]
11. An issue with serial logging enabled on RealPort serial ports that never closed the logging session has been resolved. [DAL-6748]
12. An issue that prevented SMTP notifications from using TLS encryption has been resolved. [DAL-7097]

### **VERSION 22.11.48.12 (Mar 2023)**

---

This is a **mandatory** release.

#### **NEW FEATURES**

1. Support for the TX54 5G variants has been added.  
This release can be used on all TX54 variants.

### **VERSION 22.11.48.10 (Dec 2022)**

---

This is a **mandatory** release.

#### **NEW FEATURES**

1. **ITxPT support** has been added for the TX54 and TX64 platforms. The following services are supported
  - Time Service
  - GNSS Location Service
  - MQTT Broker Service
2. Support for a **MQTT broker** has been added to the TX54 and TX64 platforms.
3. Support for a **FIPS mode** has been added to the TX64 platforms.
4. Support for using **intelliFlow** in **Digi Remote Manager** has been added.  
Note: A Digi Remote Manager Premier license is required.
5. Support for **NHRP** has been added.

6. A system watchdog that monitors critical services and resources and will reboot the system if those services or resources fail has been added.

## ENHANCEMENTS

1. DMVPN phase 1 spoke support has been added.
2. The cellular signal strength and quality statistics have been updated to make them more reactive. There is a new **Network > modem > Interface > query\_interval** has been added to allow the user to configure the rate at which it is update. The default is 30 seconds.
3. Serial port data logging options have been added to the Serial configuration to allow any sent and received on a serial port to be logged, along with the port and mode information. The previous Web UI and CLI command that allowed the serial logs to be manually started, stopped and cleared have been removed.
4. The automatic device and cellular module firmware update options are disabled if Digi Remote Manager in order to prevent conflicts with Digi Remote Manager configurations.
5. Support for enabling / disabling ICMP redirects has been added. ICMP redirects are disabled by default.
6. The CLI commands **tail** and **grep** have been added to allow for better monitoring and searching of the system log and files.
7. The container datapoints that are sent to Digi Remote Manager are now sent with the configured container name instead of the container index.
8. A modem scan timeout option has been added to the **Status > Modems > Carrier Scan** Web UI page.
9. The help text for the **Authentication > methods** has been updated to provide clarification on the mode of operation between authoritative versus non-authoritative options.
10. The error messages in the Web UI when restoring a configuration backup if the web connection is lost before receiving a response has been updated.

## SECURITY FIXES

1. The Linux kernel has been updated to 5.19 [DAL-6558]
2. The OpenSSL package has been updated to 3.0.7 on the TX64 platforms and to 1.1.1s on the TX54 and LR54 platforms. [DAL-6991]  
[CVE-2022-3786](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H
3. The shellinabox package has been updated to v2.21. [DAL-5430]  
[CVE-2018-16789](#) CVSS Score: 7.5 High CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H, CWE-835
4. The systemd package has been updated to v245. [DAL-5421]  
[CVE-2020-1712](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H, CWE-416  
[CVE-2019-3844](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H  
[CVE-2019-3843](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H  
[CVE-2018-6954](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H  
[CVE-2018-16864](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H, CWE-770  
[CVE-2018-15688](#) CVSS Score: 8.8 High CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H, CWE-119  
[CVE-2018-15686](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H, CWE-502



[CVE-2017-9445](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H, CWE-787  
[CVE-2017-9217](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H, CWE-20  
[CVE-2017-18078](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H, CWE-59  
[CVE-2017-1000082](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H, CWE-20

[CVE-2013-4391](#) CVSS Score: 7.5 High CVSS:2.0/AV:N/AC:L/Au:N/C:P/I:P/A:P, CWE-190

5. The jquery package has been updated to v3.6.1 and the jquery\_ui package 1.13.2. [DAL-5686]  
[CVE-2021-41184](#) CVSS Score: 6.1 Medium CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:N  
[CVE-2021-41183](#) CVSS Score: 6.1 Medium CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:N  
[CVE-2021-41182](#) CVSS Score: 6.1 Medium CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:N
6. An issue that allowed escalated file system access through Digi Remote Manager has been resolved. [DAL-6784]
7. The default OpenVPN server cipher has been to AES-256-GCM as AES-256-CBC has been deprecated. [DAL-5737]

## BUG FIXES

1. An issue with that caused low upload performance with Wi-Fi hotspots has been resolved. [DAL-6674]
2. An intermittent issue with the SIM failover with platforms using the Telit LM940 cellular module has been resolved. [DAL-6569]
3. An intermittent issue that meant that containers could not start due to a permission issue has been resolved. [DAL-7041]
4. An intermittent issue that prevented configuration restores from the CLI due to the output of **show config cli\_format** command giving configuration settings in the wrong order has been resolved. [DAL-6435]
5. An intermittent issue with the **digidevice.sms** Python library where it couldn't process MMS messages has been resolved. [DAL-6952]
6. An issue that prevented cellular module firmware updates when no SIM was inserted in the active SIM slot. [DAL-6309]
7. An intermittent issue that caused system performance issues when heavily utilizing VPN tunnels on the TX54 and LR54 platforms has been resolved. [DAL-5926, DAL-6534, DAL-6731]
8. An issue with the output of the **iperf** speedtests has been resolved. [DAL-7001]
9. An issue that prevented the creation of password-protected configuration backup files has been resolved. [DAL-6931]
10. An intermittent issue with the IPsec strict routing mode when a default route change could result in packet not going through the IPsec tunnel has been resolved. [DAL-6518]
11. An intermittent issue where a device configured as a L2TP LAC would drop its tunnel and not automatically reconnect has been resolved. [DAL-5415]
12. An intermittent issue when a device configured as a L2TP server would sometimes drop packets from L2TP client tunnels has been resolved. [DAL-6696, DAL-6724]
13. An issue that prevented L2TP tunnel from running if configured with a name longer than 12 characters has been resolved. [DAL-6718]

## DEPRECATION

1. The Bluetooth scanner support has been removed on the TX64 platforms. [DAL-6803]

## VERSION 22.8.33.50 (Sept 2022)

---

This is a **mandatory** release.

## NEW FEATURES

1. Support for **DMVPM** has been added.
2. Support for a **PPPoE server** in IP passthrough mode has been added.

## ENHANCEMENTS

2. Support for passive Wi-Fi background scanning on 5GHz DFS channels when DFS client support is enabled has been added.
3. Support for starting and stopping a container and getting container status using Digi Remote Manager has been added.
4. The device and cellular module firmware repository has been moved from **firmware.accns.com** to **firmware.devicecloud.com** repository.
5. New **system firmware ota download** and **modem ota download** CLI commands have been added for downloading device or cellular module firmware from the Digi firmware repository.
6. Support for sending container statistics to Digi Remote Manager has been added.
7. A new **strict routing** option has been added to the IPsec support that will only forward packets over the IPsec tunnel if both the source and destination IP addresses match the IPsec tunnel's policies instead of NATing the traffic that only matches the remote network policy.
8. A new **system power profile** configuration setting has been added for the TX64 and TX64 Rail platforms which can be used to manage the CPU frequency and power usage of the device. There are four levels
  - Auto
  - Manual
  - Power Save
  - PerformanceThe default setting is Performance.
9. A new **system power leds\_enabled** configuration setting has been added for the TX64 and TX64 Rail platforms. The LEDs can be disabled in order to reduce power consumption. When disabled, the WWAN1 Signal LED will flash every 15 seconds to indicate the device is powered up.
10. A new **show eth** CLI command has been added to display the status of each Ethernet interface.
11. A **poweroff** CLI command has been added to gracefully power down the device.

On a TX54 or TX64 that has the ignition sense line connected and is ON, the device will reboot.
12. The **5G-NSA** option has been added to the cellular access technology configuration.
13. The configuration for the speed test and firmware servers has been added to the Digi Remote Manager configuration.

14. The Cellular carrier name and PLMN ID have been added to the **Status > Modems** Web UI page.
15. A **network** configuration parameter has been added to **BGP** to allow the user to configure which networks should be advertised.
16. A configuration option has been added to enable and disable aView style SMS control messages if Digi Remote Manager is being used.
17. Support for MS-CHAPv2 authentication of remote peers on PPP answering interfaces (e.g. PPP over L2TP, PPP over Serial interfaces, PPPoE server in IP passthrough mode) has been added.
18. The ability to store kernel crash information and debug logs across reboots and automatically add them to the system logs has been added.
19. A message indicating that the **WAN Bonding** support requires a Digi Remote Manager license is now shown when in configuration Web UI page.
20. The **System > Update Firmware** Web UI page is now automatically updated when the user clicks on the **Duplicate Firmware** button.

## SECURITY FIXES

1. The OpenSSL package has been updated to 3.0.5 on the TX64 platforms and to 1.1.1q on the TX54 and LR54 platforms. [DAL-6442, DAL-6470]  
[CVE-2022-2274](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2022-2068](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H
2. The Linux kernel has been updated to 5.18 [DAL-6345]

## BUG FIXES

1. An issue with the TX54 and TX64 that prevented it from switching back from SIM2 to SIM1 has been resolved. [DAL-5945]
2. An issue that prevent TX54 and TX64 devices using the LM940 cellular module from connecting to the Verizon network has been resolved. [DAL-6186]
3. An issue with the second cellular module on the TX54 and TX64 taking a long time to connect during boot up has been resolved. [DAL-6321]
4. An issue where the SureLink **Reset modem** option would prevent the SureLink SIM failover option from taking affect if both options are enabled has been resolved. [DAL-6343]
5. An issue where the Wi-Fi Client using the second Wi-Fi module would not reconnect to a Wi-Fi Access Point if the signal is lost has been resolved. [DAL-6048]
6. Connectivity issues on a TX64 5G and TX64 Rail platforms with a Vodafone SIM where the device would switch to using Verizon firmware instead of Generic firmware has been resolved. [DAL-6603]
7. An issue with L2TP where a default route was being incorrectly added to the routing table has been resolved. [DAL-6328]
8. An issue when starting a container as a non-privileged user that would fail due permission errors has been resolved. [DAL-5844]
9. An issue where the system log could display entries in the local time and UTC time has been resolved. [DAL-6408, DAL-6520]
10. An issue that prevent the device connecting to Digi Remote Manager via a HTTP proxy over an IPsec tunnel has been resolved. [DAL-6430]

11. An issue with the TX64 Rail platform with Ethernet interfaces continually going up and down when configured in 1Gbps, full duplex mode has been resolved. [DAL-6472]
12. A CLI command line character limitation that prevented long commands or a series of commands being cut and pasted into the CLI has been resolved. [DAL-6445]
13. An issue that prevented the device from connecting to Digi Remote Manager when WAN Bonding is active has been resolved. [DAL-6386]
14. An issue when attempting to download the OpenVPN client configuration template file when the device has a default system name has been resolved. [DAL-6561]
15. An issue where manual carrier selection through the web UI, configuration settings, or Admin CLI would fail to connect if the SIM required an APN username/password with CHAP authentication has been resolved. [DAL-6535, DAL-6552]
16. An issue with sending UCS-2 formatted SMS messages with UTF-16 characters has been resolved. [DAL-6318]
17. A formatting issue with the SIM ICCID metric being sent to Digi Remote Manager has been resolved. [DAL-6394]

## **VERSION 22.5.50.62 (June 2022)**

---

This is a **mandatory** release.

### **NEW FEATURES**

1. WAN bonding support for bonding multiple WAN connections together for increased maximum throughput or redundancy has been added to the TX54 and TX64 platforms.  
Note: This support can only be enabled using Digi Remote Manager.
2. A Serial PPP dial-in mode for handling AT based connection requests from a device connected on a serial port and providing IPv4 networking to the device.

### **ENHANCEMENTS**

1. The SCEP client support has been enhanced to work with a wider range of SCEP servers.

The following SCEP servers have been tested:

- Fortinet FortiAuthenticator
- DigiCert
- EJBCA
- Windows Server

A new **show scep** CLI command has been added to display the status of the configured SCEP clients.

2. The Wi-Fi Scanner functionality has been updated to allow the Wi-Fi Scanner results to be pushed to one or more remote servers using a TCP or HTTP connections.
3. The SureLink “Reset Modem” action has been enabled by default on cellular interfaces with the fail count set to 3. The modem will be automatically power cycled in the event the modem fails to reset correctly.
4. 5G slicing support for a single slice has been added to the TX64 5G platforms.
5. The location support has been updated to support different NMEA sentence content options when forwarding the NMEA sentences to a remote server and there is no valid fix.
6. The cellular APN and connection time have been added to the data points that are uploaded

to Digi Remote Manager.

7. The Web UI has been updated to no longer display deprecated cellular modem firmware images on the Modem status page.
8. The NTP server time.accns.com has been removed from the list of default NTP servers unless the aView management system is being used.
9. A new **system.log.persistent\_path** configuration option has been added to allow the logs to be stored to a specific location including an external device like a USB flash drive.
10. The Web UI **System > Configuration Maintenance** page has been updated to improve the message displayed when an error is encountered when restoring a back configuration file.
11. The hostname of the device is now included in the OpenVPN client \*.ovpn configuration file on the WebUI **Status > OpenVPN > Servers** page.
12. Support for connecting to the Cisco USB Console ports has been added.
13. The APN fallback list has been updated to remove the non-Internet type APNs.

## SECURITY FIXES

1. The OpenSSL package on the TX64 has been updated to 3.0.2.
2. The OpenSSL package on the TX54 and LR54 platforms has been updated to 1.1.1o. [DAL-6303]
3. The Linux kernel has been updated to 5.17 [DAL-6081]
4. A Linux kernel patch for the “dirty pipe” vulnerability has been added. [DAL-5981]  
[CVE-2002-0847](#) CVSS Score: 7.5 High CVSS:2.0/AV:N/AC:L/Au:N/C:P/I:P/A:P
5. The OpenVPN package has been updated to 2.5.6. [DAL-6229]  
[CVE 2022-0547](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H
6. The gcc tools have been updated to 11.2 and the binutils tools has been updated to 2.37. [DAL-5444]  
[CVE-2019-15847](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N, CWE-331  
[CVE-2018-12886](#) CVSS Score: 8.1 High CVSS:3.0/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:H/A:H, CWE-209  
[CVE-2002-2439](#) CVSS Score 7/8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H, CWE-190

## BUG FIXES

1. An issue with the location support for devices configured with a non-UTC timezone which would report an incorrect UTC time when receiving TAIP messages. [DAL-6267. DAL-6335]
2. An issue with missing RSSI values for SSIDs for SSIDs found by the Wi-Fi Scanner when used on a Wi-Fi 6 module has been resolved. [DAL-6030]
3. An issue where an IPsec tunnel failing to reestablish the tunnel if the SAs are deleted after phase 1 re-authentication has been resolved. [DAL-4959]
4. An issue where the connection to Digi Remote Manager could be delayed up to 15 minutes before refreshing to use the active main WAN connection in the event of a network failover or fallback has been resolved. [DAL-6164]
5. An issue with the default Wi-Fi AP SSIDs being too long on the TX64 Rail platform has been resolved. [DAL-6329]
6. An issue where OpenVPN > Advanced options > OpenVPN parameters text box was limited to

64 characters when synced with Digi Remote Manager has been resolved. The limited is now 64,000 characters. [DAL-6002]

7. An issue resulting from a race condition when disconnecting from Digi Remote Manager which could cause the Cloud Connector firmware to crash has been resolved. [DAL-5971]
8. An issue that could prevent Wi-Fi Hotspots from initializing correctly has been resolved. [DAL-6306, DAL-6313]
9. An issue that prevented an OpenVPN server from authenticating clients with an external LDAP, TACACS+ or RADIUS server has been resolved. [DAL-6159]
10. An issue that prevented LDAP external authentication for SSH and Telnet sessions has been resolved. [DAP-6098]
11. The **show containers** CLI command has updated to list all containers on the file system and not just those link to configuration settings.
12. Broken links on the Web UI for Digi Remote Manager on the Dashboard and **System > Digi Remote Manager** have been resolved. [DAL-6088]
13. An issue preventing an interface's MAC address **allowlist** from implicitly denying access to devices not in the allowlist has been resolved. [DAL-6001]
14. An issue with Python digidevice.config module which could result in a segmentation fault has been resolved. [DAL-6005]

## **VERSION 22.2.9.85 (March 2022)**

---

This is a **mandatory** release.

### **NEW FEATURES**

15. The internal GNSS module on the TX54 and TX64 platforms can now be used as a time source for the NTP server support.

### **ENHANCEMENTS**

1. Added a SureLink option to switch SIMs if the SureLink tests fail for a configured number of times.
2. A set of new container CLI commands have been added to create, delete and interact with containers.
3. The default URL for Digi Remote Manager has changed to edp12.devicecloud.com.
4. The SCEP client support has been updated with two new settings to allow the user to configure a CA identity and the HTTP URL path for the CA.
5. A debug configuration option has been added to the IPsec support to allow the user to debug an IPsec tunnel.
6. A new serial port option has been added to send a configured string to a remote server when a TCP socket connection is opened on the serial port.
7. The location support has been enhanced with the following new settings
  - UDR support enable/disable (default: disabled)
  - Automatic attenuation enable/disable (default: enabled)
  - Minimum satellite signal level required for navigation (default: 6 dBHz)
  - Minimum number of satellites required for navigation (default: 3)

- Maximum number of satellites required for navigation (default: 18)
8. The ability for policy-based routes to override the routing of packets through VPN tunnels has been added. This is useful in the case where you only want packets from a certain source network to go through the VPN tunnel.
  9. A new TX54 and TX64 **system power ignition off\_delay** CLI command has been added to allow the devices power off delay to updated without the configuration being updated. This means the next device reboot it will revert to its configured power off delay.
  10. A new configuration setting has been added to allow the user to specify the minimum TLS version that can be used with the Web UI. By default, the minimum is TLS 1.2.
  11. If a Sprint Curiosity SIM is being used, T-Mobile carrier firmware will now be used if available.
  12. A new **cat** CLI command has been added for displaying the contents of a file.

## SECURITY FIXES

1. The DNSMasq package has been updated to version 2.86 [DAL-5331]  
[CVE-2021-3448](#) CVSS Score: 4.0 Medium CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:C/C:N/I:L/A:N
2. The OpenSSH package has been updated to version 8.8p1 [DAL-5451]  
[CVE-2021-28041](#) CVSS Score: 7.1 High CVSS:3.1/AV:N/AC:H/PR:L/UI:R/S:U/C:H/I:H/A:H  
[CVE-2020-14145](#) CVSS Score: 5.9 Medium CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:H/I:N/A:N
3. The Linux kernel has been updated to 5.15 [DAL-5546]
4. The Busybox package has been updated to version 1.34.0 [DAL-5631]  
[CVE-2021-42373](#) CVSS Score: 5.5 Medium CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:N/I:N/A:H  
[CVE-2021-42374](#) CVSS Score: 5.3 Medium CVSS:3.1/AV:L/AC:H/PR:L/UI:N/S:U/C:L/I:N/A:H  
[CVE-2021-42375](#) CVSS Score: 5.5 Medium CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:N/I:N/A:H  
[CVE-2021-42376](#) CVSS Score: 5.5 Medium CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:N/I:N/A:H  
[CVE-2021-42377](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42378](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42379](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42380](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42381](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42382](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42383](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42384](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42385](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H  
[CVE-2021-42386](#) CVSS Score: 7.2 High CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H
5. The dbus package has been updated to version 1.13.20 [DAL-5459]  
[CVE-2020-12049](#) CVSS Score: 5.5 Medium CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:N/I:N/A:H  
[CVE-2019-12749](#) CVSS Score: 7.1 High CVSS:3.0/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:N
6. The GRUB package has been updated to version 2.06 [DAL-5456]  
[CVE-2021-3418](#) CVSS Score: 6.4 Medium CVSS:3.1/AV:L/AC:H/PR:H/UI:N/S:U/C:H/I:H/A:H
7. The bzip2 package has been updated to version 1.08 [DAL-5446]  
[CVE-2019-12900](#) CVSS Score: 9.8 Critical CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H  
[CVE-2011-4089](#) CVSS Score: 4.6 Medium CVSS:2.0/AV:L/AC:L/Au:N/C:P/I:P/A:P



[CVE-2010-0405](#) CVSS Score: 5.1 Medium CVSS:2.0/AV:N/AC:H/Au:N/C:P/I:P/A:P

8. The procps package has been updated to version 3.3.15 [DAL-5433]

[CVE-2018-1123](#) CVSS Score: 7.5 High CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2018-1124](#) CVSS Score: 7.8 High CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:H/A:H

[CVE-2018-1125](#) CVSS Score: 7.5 High CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

[CVE-2018-1126](#) CVSS Score: 9.8 Critical CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H

9. The OpenSSL build has been updated to include secure compilation flags. [DAL-5472]

## BUG FIXES

1. An issue where the TCP socket to location servers were not being properly closed between location messages has been resolved. [DAL-5716]
2. An issue that prevented the device from updating the maintenance window status with Digi Remote Manager if the maintenance window start time was between 00:00-00:59 has been resolved. [DAL-5765]
3. An issue with IPsec where only the first policy would be setup on tunnels using IKEv2 has been resolved. [DAL-5347]
4. An issue preventing IPsec transport mode tunnels from initializing properly has been resolved. [DAL-5718]
5. An issue with SureLink DNS tests that could prevent an interface from coming up has been resolved. [DAL-5934]
6. An issue with QoS HFSC setup to limit bandwidth user for shared links has been resolved. [DAL-5814]
7. An issue preventing port forwarding firewall setups if the destination port(s) setting was left blank has been resolved. [DAL-5680]
8. An issue that where the TX54 and LR54 platforms failing to negotiate with some 10Mbps Ethernet switches has been resolved. [DAL-5506]
9. An issue with the Web UI allowing invalid Modbus client filter values to be configured has been resolved. [DAL-5905]
10. An issue with the Python digidevice SMS module where the callback stops working after a number of SMS messages have sent or received has been resolved. [DAL-5883]
11. An intermittent issue with the **show dhcp-leases** command where not all of the leases were being displayed has been resolved. [DAL-5688]
12. An issue preventing persistent containers from initializing has been resolved. [DAL-5847]
13. An issue with **sh: out of range** was being outputted when starting the test\_lxc container has been resolved. [DAL-5845]
14. An issue with the CLI when a TACACS+ server is not configured correctly has been resolved. [DAL-5512]
15. An issue with interruptions of active serial port connections when changes are made to the serial port mode has been resolved. [DAL-5698]
16. An issue preventing MMS SMS message from being received and parsed properly, preventing large out-of-band configuration changes from being from aView/ARMT has been resolved. [DAL-5538]



For information on earlier firmware versions, please visit <https://www.digi.com/support>